

ORDER 20169990

UNPLANNED MAINT. <InternalOrderSettlem.>



BUS2007-000020169990-PRD

Order	20169990	Ord.type	PM06	
Sup. Order		Act.type	P03	
Planning grp	H80	M.Plan		
Priority	1	Item		Main WC STABO001
STATUS	REL ESTC NMAT PRC SETC			
Description	BORDOVSKY STAB. LDAR T-13201			

DUE DATE 04/16/2014

Func. Loc.	HZ-T0-EGF-A069254	Location	
	BORDOVSKY STABILIZER	Room	
	OCC/TRRC Number		
	Field Name		
	Meter ID Number		
Equipment	12076102	Cost Center	A657269
	TANK CONDENSATE T-10206	ABC ind.	A
	Begin Guarantee		
	Warranty End		

Sort Field
 Manufacturer : STX PROCESSING EQ
 Manuf. Serial no: OC260
 Model no : T-10206
 Technical ID no:
 Size/Dimension : 12'X25'

Operation list

Op	Sub	Description	Workcenter
0010		BORDOVSKY STAB. LDAR T-13201	MECHAPSM

BORDOVSKY STAB. LDAR T-13201

Attached you will find the Requests For Repair for the Bordovsky Facility Leak Inspection (04-16-2014). Please fax, call or email the completed forms with the repair actions, date and time as indicated on the bottom of the form to the "Irvine Office". Please note the repair time frame for each leak is 15 days. Upon the repair, Avanti will return to re-inspect the repaired leaks. If you have any questions or concerns, please feel free to contact me at (210) 438-2850.

Kind Regards,

Javier Ramirez
 Avanti Environmental, Inc.
 Field Technician
 TOP OF TANK #13201, 12" HATCH IS LEAKING FROM SEAL. LOCATED ON THE TOP SOUTH SIDE OF TANK.
 (SEE GREEN TAG ON COMPONENT)

END OF ORDER